A00 - 4-77

## U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

CONFIDENTIAL CONTINULA

## MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SECT	ION I
MANUFACTURER'S NAME	EMERGENCY TELEPHONE NO.
Products Research & Chemical Corp.	(213) 849-3992
ADDRESS (Number, Street, City, State, and ZIP Code) 2919 Empire Ave., Burbank, Calif. 91504	
CHEMICAL NAME AND SYNONYMS Polysulfide sealing compound.	PR-1422 Class A
CHEMICAL FAMILY N/A	FORMULA N/A

SECTION	J 11 -	HAZAF	RDOUS INGREDIENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	VENTS % TLV   ALLOYS AND METALLIC COATINGS		%	TLV (Units)	
PIGMENTS		·	BASE METAL		
CATALYST Calcium Dichromate	4	0.1mg/	ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS Toluene	7	200ppm	FILLER METAL PLUS COATING OR CORE FLUX		
жжжжжж Methyl ethyl ketone	2	200ppm	OTHERS		
отнекs Dimethyl formamide	2	10ppm			
HAZARDOUS MIXTURE	S OF	OTHER LIC	DUIDS, SOLIDS, OR GASES	1 %	TLV (Units)
			-		
	· · · · · ·				
•					

	SECTION III - I	PHYSICAL DATA	
BOILING POINT (2F.)	N/A	SPECIFIC GRAVITY (H2O=1)	1.42
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT, VOLATILE BY VOLUME (%)	16.5%
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE (=1)	N/A
SOLUBILITY IN WATER	Insol.	•	

SECTION IV - FIRE AND E	XPLOSION HAZARD DA	TA	
FLASI: POINT (Method used) 23°F (PMCC)	FLAMMABLE LIMITS	L,el	Uel -/
EXTINGUISHING MEDIA  Dry chemical, foam,	CO <sub>2</sub>		
SPECIAL FIRE FIGHTING PROCEDURES	•		
	•		
UNUSUAL FIRE AND EXPLOSION HAZARDS CEN emit	coxic vapers.		

SECTION V - HEALTH HAZARD DA	ATA
THRESHOLD LIMIT VALUE 200 ppm	
EFFECTS OF OVEREXPOSURE  Headache: possible skin irritation	
EMERGENCY AND FIRST AID PROCEDURES SKIN: Wash thoroughly with soap and water.	
EYES: Wash out immediately with plenty of water; see	a physician.
INHALATION: Remove to fresh air.	

·	•		SECTIO	N VI - R	EACTIVITY DATA	•
STABILITY	TY UNSTABLE CO		CONDITION	ONDITIONS TO AVOID		
STABLE X		χ			·	
INCOMPATABILITY	' (Materi	als to avoid)	Can r	eact wit	h reducing materi	als.
HAZARDOUS DECC	MPOSIT	TION PRODUC	oxide	s of sul	fur; hydrogen sul	fide ,formic acid.
HAZARDOUS		MAY OCCUR			CONDITIONS TO AVOID	
POLYMERIZATION	F	WILL NOT O	CUR	X		
		•				

SECTION VII - SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
Wipe up with rags or paper towels; clean with MEK.
WASTE DISPOSAL METHOD
Closed containers in normal trash route.
Do not incinerate.

	SECTION VIII - SPECIA	AL PROTECTION	INFORMATION
	ROTECTION (Specify type)	area	
VENTILATION	d respirator in enclosed area. LOCAL EXHAUST Adequate to minimize vapors.		SPECIAL
12- 12- 12- 12- 12- 12- 12- 12- 12- 12-	MECHANICAL (General)	•	OTHER
PROTECTIVE GLI	oves hand cream.	EYE PROTECT Chemical of	on goggles optional.
OTHER PROTECT	IVE EQUIPMENT		

SECTION IX - SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING  Keep in closed containers in sheltered area.
Keep away from heat and open flame.
OTHER PRECAUTIONS  Avoid prolonged skin contact. Avoid prolonged or repeated breathing of vapor.

PAGE (2)

Form OSHA-20 Rev. May 72